TESTING DISPLAY:

 - disconnect from blackbox
- RED cabel connect on +12V
- each pin from display connector connect throw 500 OHM resistor on -12V (ground)
      every pin when grounded should light one segment (line) of digit

- if all segments lights is problem in black box - if still missing segments is display fault