




Weight on shifting shaft must be cutted-off !



Replace the rivet in fork 1°-2° by delivered bolt, secure the nut by LOCTITE !  
Hole in fork must be redriled to 8mm !



Replace complete fork 3°-4° by delivered Alu, secure by double pins !



The 4° gearbox has empty space on position 5°-6°, if it is used SEQSHIFT (SQS or SQS-E) be sure it is 4° version !

If shifting is H pattern – block engaging 5°-6° line by installing bolt in shifter casing on this place.

